### TECHNICAL LIBRARY

AD A-107037

#### TECHNICAL REPORT ARBRL-TR-02370

# EFFECTIVENESS TESTING FOR ANTIPROPAGATION SHIELDS DEVELOPED FOR M456 HEAT TANK AMMUNITION

Jerry Thomas Philip M. Howe

September 1981



## BALLISTIC RESEARCH LABORATORY ABERDEEN PROVING GROUND, MARYLAND

Approved for public release; distribution unlimited.

Destroy this report when it is no longer needed. Do not return it to the originator.

Secondary distribution of this report by originating or sponsoring activity is prohibited.

Additional copies of this report may be obtained from the National Technical Information Service, U.S. Department of Commerce, Springfield, Virginia 22151.

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The use of trade names or manufacturers' names in this report does not constitute indorsement of any commercial product.

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE (When Dete	Entered)							
REPORT DOCUMENTATION	READ INSTRUCTIONS BEFORE COMPLETING FORM							
1. REPORT NUMBER	3. RECIPIENT'S CATALOG NUMBER							
Technical Report ARBRL-TR-02370								
4. TITLE (and Subtitie)		S. TYPE OF REPORT & PERIOD COVERED						
EFFECTIVENESS TESTING FOR ANTIPROPA DEVELOPED FOR M456 HEAT TANK AMMUNI		Final						
	6. PERFORMING ORG. REPORT NUMBER							
7. AUTHOR(*) Jerry Thomas Philip M. Howe		8. CONTRACT OR GRANT NUMBER(a)						
9. PERFORMING ORGANIZATION NAME AND ADDRESS US Army Ballistic Research Laborato (ATTN: DRDAR-BLT/V) Aberdeen Proving Ground, MD 21005		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS  RDT&E 1L162618AH80						
US Army Armament Research and Devel US Army Ballistic Research Laborato (ATTN: DRDAR-BL)	opment Command	12. REPORT DATE September 1981						
(ATTN: DRDAR-BL)	ry	13. NUMBER OF PAGES 47						
Aberdeen Proving Ground MD 21005 14. MONITORING AGENCY NAME & ADDRESS(If different	nt from Controlling Office)	15. SECURITY CLASS. (of this report)						
·		UNCLASSIFIED						
		15. DECLASSIFICATION/DOWNGRADING SCHEDULE						
16. DISTRIBUTION STATEMENT (of this Report)								
Approved for public release; distri	bution unlimited							
17. DISTRIBUTION STATEMENT (of the abetract entered	in Block 20, if different fro	m Report)						

18. SUPPLEMENTARY NOTES

19. KEY WORDS (Continue on reverse elde it necessary and identity by block number)
shielding thickness quantal response
round-to-round propagation experimental design M456 HEAT tank ammunition
extreme value design antipropagation

Modified Alexander Extreme Value Design

Numerous previous tests demonstrated the effectiveness of polyethylene bars emplaced between rounds of M456 HEAT tank ammunition to prevent a second round detonation given the detonation of a first round. However, these tests had a considerable margin of safety and the reliability and associated confidence level were unknown. In this report, a description is given of the statistical design and tests which were performed to establish the shielding thickness needed to be 90% confident that the probability of a second round detonating, given a first round detonation, was less than 0.1.

#### TABLE OF CONTENTS

		Page
	LIST OF ILLUSTRATIONS	5
I.	INTRODUCTION	7
II.	TEST CRITERIA AND EXPERIMENTAL TECHNIQUE	7
III.	STATISTICAL DESIGN	10
IV.	RESULTS	11
V.	CONCLUSIONS	11
	APPENDIX	13
	DISTRIBUTION LIST	45

#### LIST OF ILLUSTRATIONS

Figur	e	Pa	ge
1.	Typical Test Setup	•	8
2.	Method of Detonation of Donor M456, 105 mm HEAT-T H.E. Projectile, Comp B Loaded with Fuze		9
3.	Summary of Test Results		12

#### I. INTRODUCTION

In previous work, conducted for the Ml Tank Project Office (then the XM1), it was demonstrated that detonation of nearest neighbor rounds as a result of detonation of a donor round could be prevented for M456 HEAT warheads by use of polyethylene bars emplaced between each round<sup>1</sup>. While numerous tests demonstrated the effectiveness of the plastic bars, and the thicknesses used contained a considerable margin of safety, the reliability and associated confidence level were unknown. In this effort, we describe a statistical design and tests which were performed to establish the shielding thickness needed to be 90% confident that the probability of a second round detonating, given the detonation of a first round, was less than 0.1.

#### II. TEST CRITERIA AND EXPERIMENTAL TECHNIQUE

The criterion for successful shielding was that the acceptor rounds not detonate. Thus, reactions of severity less than that of a design-mode detonation, although not necessarily desirable, were considered acceptable. The basis for this choice was the fact that reactions less severe than detonations will not cause further rounds to detonate, and the process of propagation from round-to-round ceases<sup>2</sup>.

A typical test set up is shown in Figure 1. The donor round was deliberately detonated using a small charge of C-4 explosive, an RDX booster, and P-3 detonating cord as the initiator. The method of initiation is shown schematically in Figure 2. Shielding thicknesses were varied from test to test, according to the design methodology. Shields were fabricated from sheets of polyethylene of various thicknesses, e.g., a 2.54 cm thick shield was fabricated from two 1.27 cm thick slats, and a 1.59 cm thick shield was fabricated from a 1.27 cm thick slat in contact with a 0.32 cm thick slat. Especial care was taken to insure that the donor and acceptor rounds were in contact with the shielding material. Thus, when shielding thickness was varied, spacing between rounds was varied correspondingly. (This represents a more severe testing case than if the spacing were kept constant.) Tests which involved more than two acceptors had 1.27 cm mild steel plates emplaced between them to prevent cross talk between acceptors in the event that one detonated (see the data sheet for test KAAO331A1, in the Appendix, for a schematic).

Photographs were taken of each test before and after deliberate detonation of the donor round. The response of the acceptor rounds was evaluated by examination of the acceptor fragments (when found) and by examination of the witness plates. Both fragment size and witness plates provided unambiguous assessments of munition response. Thus, when acceptors reacted mildly, or not at all, the acceptors were squashed, cracked open, or broken into several very large pieces. The witness plate behind the acceptor (viewed from the donor)

<sup>&</sup>lt;sup>1</sup>Howe, P., "The Phenomenology of Interround Communication and Techniques for Prevention," ARBRL-TR-02048 (1978) (AD #A054373).

<sup>&</sup>lt;sup>2</sup>This fact has not, as yet, been documented anywhere. It is the conclusion of one of the authors (P. Howe) based on several years of effort in studying propagation mechanisms.




Figure 1 - Typical Test Setup




Figure 2 - Method of Detonation of Donor M456, 105 mm HEAT-T H.E. Projectile, Comp B Loaded with Fuze

was frequently coated with explosive. In the regions of the witness plates shadowed from the donor by the acceptors, there were no fragment perforations. This was true both for side witness plates and base witness plates. Compare, for example, the damage to the witness plates in test No. KAA0330El, where the acceptor round detonated (Appendix, p. 21) and test No. KAA0331Al, where none of the three acceptors detonated (Appendix, p. 23).

#### III. STATISTICAL DESIGN

The purpose of the test, as previously stated, was "to establish the shielding thickness needed to be 90% confident that the probability of a second round detonating, given the detonation of a first round, was less than 0.1." Since the probability of interest was  $\alpha$  = 0.1, and is therefore in the tail of some unknown response distribution, the problem appeared to fit into the category of extreme value quantal response designs. Quantal response means that the result has only two possible choices, in this case detonation or nondetonation. Also, because of the lack of information about the response function, a nonparametric test design was used, Modified Alexander Extreme Value (MAEV) Design.

The MAEV design rules are given below. (For more detail, see reference 3.)

- 1. The first test level is  $X_r$ , the best a priori guess of  $X_\alpha$ .  $X_\alpha$  is the shielding thickness where the probability of a response (detonation) is  $\alpha = 0.1$ .  $\delta = 3.18$  mm is the step size between levels.
- 2. One acceptor per donor is used, in a decreasing shielding thickness sequence, until a response is observed. Let  $\mathbf{X}_d$  be the highest level at which a response is observed.
- 3. After the first response, the number of acceptors per donor in each test is increased to alternately three and then four. After the first response, three acceptors per donor are tested at the next three levels above  $\mathbf{X}_{\mathbf{d}}$ . Then four acceptors per donor having shielding at levels  $\mathbf{X}_{\mathbf{d}}$  and the next three higher levels are tested.
- 4. If another response is observed at a higher level, it becomes  $\mathbf{X}_{\mathbf{d}}$ , and testing continues alternating three and then four acceptors per donor until at least 12 (more than half the required 22) nonresponses have been observed at the two levels immediately above  $\mathbf{X}_{\mathbf{d}}$ .
- 5. When at least 12 nonresponses have occurred at  $x_d$  +  $\delta$  and  $x_d$  +  $2\delta$ , the number of acceptors per donor is reduced to alternately two above  $X_d$  and then three, starting at  $X_d$ , for the remainder of the test.
- 6. Testing terminates when at least N (22) nonresponses have been observed at the two levels immediately above the highest level at which a response has been observed.

<sup>&</sup>lt;sup>3</sup>Smith, J. H. and Thomas, J., "Extreme Value Quantal Response Experimental Design," ARBRL-TR-02325 (1981). (AD #A101188)

The 22 nonresponses were arrived at in the following manner. If the probability of a response at  $X_{\alpha}$  is equal to  $\alpha$ , then the probability of not getting a response is  $1-\alpha$ . Assuming the tests are independent, the probability of n nonresponses in n tests is  $(1-\alpha)^n$ . Then,  $1-(1-\alpha)^n=P$ , is the probability of at least one response in n tests. In our case, P=0.9 and  $\alpha=0.1$ . Solving for n and letting N=[n]+1, we get N=22. Thus, after observing 22 nonresponses at  $X_d+\delta$  and  $X_d+2\delta$ , we can conclude that the level at which the true probability of response is 0.1 is less than  $X_d+2\delta$  with ninety percent confidence.

#### IV. RESULTS

A summary of the test results is given in Figure 3. The first test, KAAO330A1, had a shielding of 22.23 mm thick between the acceptor and the donor round. The acceptor did not detonate. The shielding thickness was decreased to 15.88 mm for the second test and to 12.70 mm for the third test with no detonation in either test. The acceptor round detonated on the fourth test with a shielding thickness of 9.53 mm between the acceptor and donor.

In all, 14 tests were conducted using 34 acceptors and 14 donors. No acceptor rounds detonated with shielding thickness greater than 9.53 mm between the acceptor and donor round. Of the six rounds tested with shielding thickness of 9.53 mm, four detonated and two did not detonate.

#### V. CONCLUSIONS

- 1. It was demonstrated that polyethylene bars between M456 HEAT rounds would prevent detonation of the second round if the bar was thick enough.
- 2. It was estimated that the probability of a second round detonating, given the detonation of a first round, to be less than 0.1 with 90% confidence if the shielding thickness is 15.88 mm or more.

## POLYETHYLENE SHIELDING THICKNESS (mm)

	3.18	6.35	9.53	12.70	15.88	19.05	22.23
ROUND NO.							
KAA0330A1							0
KAA0330B1					0		
KAA0330D1				0			
KAA0330E1			Х				
KAA0331A1				0	0	0	
KAA0331B1			Х	0	0	0	
KAA0331C1				0	0	0	
KAA0331D1			Х	0	0	0	
KAA0331E1				0	0	0	
KAA0331F1			0	0	0		
KAA0331G1				0	0		
KAA0331H1			0	0	0		
KAA0331I1				0	0		
KAA0331J1			Х	0	0		

X: DETONATION
O: NON-DETONATION


Figure 3 - Summary of Test Results

#### APPENDIX

#### COMPARTMENTALIZATION SHIELDING TEST

DATA	SHEETS ANI	) [	AN	1AC	ΞE	Pŀ	lO1	09	5																		Page
	KAA0330A1		•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•			•	•	14
	KAA0330B1				•				•				•												•	•	16
	KAA0330D1				•	•			•	•	•													•		•	18
	KAA0330E1				•	•	•	•	•	•	•	•		•		•			•	•		•	•	•			20
	KAA0331A1								•		•	•					•	•	•	•	•	•	•				22
	KAA0331B1	•	•		•	•			•		•	•	•	•	•	•	•		•	•	•	•	•	•		•	24
	KAA0331C1	•	•		•		•	•	•	•	•	•		•	•	•	•		•	•	•	•	•	•		•	27
	KAA0331D1	•		•		•	•		•		•	•			•		•	•	•	•	•	•	•	•			29
	KAA0331E1					•							•	•	•		•	•		•	•		•	•		•	32
	KAA0331F1			•	•	•	•	•	•	•							•		•	•					•		34
	KAA0331G1			•			•	•	•	•	•				•		•	•		•	•	•	•	•		•	36
	KAA0331H1		•	•	•	•			•		•	•	•	•					•								38
	KAA0331I1	•							•	•	•	•		•			•		•	•					•	•	40
	KAA0331J1																										42

TEST NO: KAAU330A1 DATE: 30 MARCH 1981 TIME: 1145 MST



Xr = 22.23mm

(Witness plates are 2.67mm thick mild steel)

RESULTS: Acceptor round did not detonate and was recovered almost intact. The projectile was blown open above the rotating band. The standing witness panel had one large perforation, and unburned explosives were deposited on it. The base witness plate had a tailfin imprint from the detonation of the donor round.

TEST NO: KAA0330A1

DATE: 30 MARCH 1981




DONOR AND ACCEPTOR PROJECTILES BEFORE TEST

ACCEPTOR FROJECTILE RECOVERED AFTER TEST




TEST NO: KAA0330B1 DATE: 30 MARCH 1981 TIME: 1145 MST



Xr = 15.88mm

(Witness plates are 2.67mm thick mild steel)

RESULTS: Acceptor round did not detonate. A large side fragment and large segment of the boom from the acceptor round were recovered. Several large perforations and unburned and burned explosive were apparent on the standing witness panel. The base witness plate had a tailfin imprint from the detonation of the donor round.



TEST NO: KAA0330B1


DATE: 30 MARCH 1981

DONOR AND ACCEPTOR PROJECTILES BEFORE TEST



FRAGMENTS OF ACCEPTOR PROJECTILE RECOVERED AFTER TEST

TEST NO: KAA0330D1 DATE: 30 MARCH 1981 TIME: 1530 MST



Xr = 12.70mm

(Witness plates are 2.67mm thick mild steel)

RESULTS: Acceptor round did not detonate. The witness panel adjacent to the acceptor round had several large perforations and some unburned H.E. deposited on it. There was a tailfin imprint left on the base witness plate by the detonation of the donor round.



TEST NO: KAA0330D1

DATE: 30 MARCH 1981


DONOR AND ACCEPTOR PROJECTILES BEFORE TEST



FRAGMENTS OF ACCEPTOR PROJECTILE RECOVERED AFTER TEST

TEST NO: KAA0330E1

DATE: 30 MARCH 1981 TIME: 1630 MST



Xr = 9.53mm


(Witness plates are 2.67mm thick mild steel)


RESULTS: Acceptor round detonated. The witness panel had many small perforations in it, but no H.E. was deposited on it. There were two tailfin imprints made in the base witness plate by the detonation of the donor and the acceptor rounds.



DATE: 30 MARCH 1981








KAA0330E1

WITNESS PANEL WHICH STOOD ADJACENT TO ACCEPTOR PROJECTILE

IMPRINTS MADE ON BASE WITNESS PLATE BY THE DETONATIONS OF THE DONOR AND ACCEPTOR PROJECTILES

TEST: KAA0331A1 DATE: 31 MARCH 1981 TIME: 0905 MST



(Witness plates are 2.67mm thick mild steel)

RESULTS: None of the acceptor rounds detonated. The witness panels which were adjacent to the acceptor rounds all had several large perforations. Unburned H.E. was deposited on the witness panels adjacent to  $A_2$  and  $A_3$ , but no H.E. remained on the witness panel adjacent to  $A_1$ .

TEST NO: KAA0331A1

DATE: 31 MARCH 1981






FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST



BASE WITNESS PLATE AFTER TEST

TIME: 1000 MST TEST: KAA0331B1 DATE: 31 MARCH 1981




(Witness plates are 2.67mm thick mild steel)

RESULTS: Acceptor round  $A_1$  detonated. Fragments from the other acceptor rounds were recovered. The standing witness panel adjacent to  $A_1$  had many small perforations. The witness panel adjacent to  $A_2$  had several large perforations. The witness panels adjacent to  $A_3$  and  $A_4$ had several large perforations and some unburned H.E. deposited on them. The base witness plate had tailfin imprints where  $A_1$  and the donor round had detonated.

TEST NO: KAA0331B1

DATE: 31 MARCH 1981




DONOR AND ACCEPTOR PROJECTILES BEFORE TEST

FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST




TEST NO: KAA0331B1

DATE: 31 MARCH 1981




WITNESS PANEL WHICH STOOD ADJACENT TO ACCEPTOR PROJECTILE, A<sub>1</sub>



BASE WITNESS PLATE AFTER TEST

TEST: KAA0331C1 DATE: 31 MARCH 1981 TIME: 1110 MST



Xr=12.70mm  $\delta=3.18$ mm H.E. PROJECTILES,  $Xr+\delta=15.88$ mm  $Xr+2\delta=19.05$ mm COMP B LOADED WITH FUZE

(Witness plates are 2.67mm thick mild steel)

RESULTS: None of the acceptor rounds detonated. The witness panel adjacent to  $A_1$  had no perforations, nor was H.E. deposited on it. The witness panel adjacent to  $A_2$  had two large perforations, and a small amount of unburned H.E. was deposited on it. The witness panel adjacent to  $A_3$  had several large perforations, and some burned and unburned H.E. was deposited on it. A tailfin imprint was left in the base witness plate by the detonation of the donor round.


TEST NO: KAA0331C1

DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST

FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST



DATE: 31 MARCH 1981 TIME: 110 MST TEST: KAA0331D1 Xr+8 POLYETHYLENE BASE WITNESS SHIELDING Xr+28 PLATE POLYETHYLENE STANDING SHIELDING WITNESS **PLATES** Xr POLYETHYLENE SHIELDING DONOR A. DONOR AND ACCEPTOR PROJECTILES: M456, 105mm HEAT-T H.E. PROJECTILES, COMP B LOADED WITH FII7F 1.27cm THICK Xr+38 STEEL SHIELDS TO POLYETHYLENE STANDING WITNESS PREVENT ACCEPTOR SHIELDING REACTION PROPAGATION **PLATES** Xr = 9.53mm $\delta = 3.18$ mm  $Xr+\delta = 12.70mm$  $Xr+2\delta = 15.88mm$  $Xr + 3\delta = 19.05mm$ (Witness plates are 2.67mm thick mild steel) RESULTS: Acceptor round  $A_1$  detonated. The witness panel adjacent to  $A_1$  has many small perforations; no H.E. was deposited on it. The witness panels adjacent to A2 and A3 had several large perforations, and some burned and unburned explosives were deposited on them. The witness panel adjacent to A4 had several large perforations, but no H.E. was deposited on it. There were tailfin imprints eft by the detonation of A<sub>1</sub> and the donor round.

TEST NO: KAA0331D1

DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST

FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST



TEST NO: KAA0331D1

DATE: 31 MARCH 1981




STANDING WITNESS PANEL WHICH STOOD ADJACENT TO ACCEPTOR A<sub>1</sub>

BASE WITNESS PLATE AFTER TEST



TEST: KAA0331E1 DATE: 31 MARCH 1981 TIME: 1400 MST



Xr = 9.53mm  $\delta = 3.18$ mm H.E. PROJECTILES,  $Xr+2\delta = 12.70$ mm  $Xr+3\delta = 15.88$ mm COMP B LOADED WITH FUZE

(Witness plates are 2.67mm thick mild steel) RESULTS: None of the acceptor rounds detonated. The witness panel adjacent to  $\mathsf{A}_1$  had a large perforation; some burned and some unburned H.E. was deposited on it. The witness panel adjacent to  $\mathsf{A}_2$  had several large perforations, and some burned H.E. was deposited on it. The witness panel adjacent to  $\mathsf{A}_3$  was not perforated; there was burned and unburned H.E. deposited on it. The base witness plate had a tailfin imprint from the detonation of the donor round.




TEST NO: KAA0331E1

DATE: 31 MARCH 1981

DONOR AND ACCEPTOR PROJECTILES BEFORE TEST


FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST





BASE WITNESS PLATE AFTER TEST

TEST: KAA0331F1 DATE:31 MARCH 1981 TIME: 1450 MST



(Witness plates are 2.67mm thick mild steel) RESULTS: None of the acceptor rounds detonated. There were two large perforations in the witness panel adjacent to  $A_1$ , but there was no H.E. deposited on it. There were several large perforations in the witness panel adjacent to  $A_2$ , and there was some burned and some unburned H.E. deposited on it. A tailfin imprint in the base witness plate was left by the detonation of the donor round.

TEST NO: KAA0331F1

DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST

FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST






BASE WITNESS PLATE AFTER TEST

TEST: KAA0331G1

DATE: 31 MARCH 1981 TIME: 1515 MST



 $Xr + 2\delta = 15.88mm$ 

(Witness plates are 2.67mm thick mild steel)

RESULTS: Neither of the acceptor rounds detonated. There were several large perforations in all the witness panels. There was burned H.E. on the witness panel adjacent to  $A_2$ . There was a tailfin imprint on the base witness plate from the detonation of the donor round.

TEST NO: KAA0331G1


DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST



TEST: KAA0331H1 DATE: 31 MARCH 1981 TIME: 1540 MST



 $Xr+2\delta = 15.88mm$ 

(Witness plates are 2.67mm thick mild steel)

**RESULTS:** None of the acceptor rounds detonated. The witness panels adjacent to  $A_1$  and  $A_2$  had some burned and some unburned H.E. deposited on them, but there were no perforations. The witness panel adjacent to  $A_3$  had one large perforation and a small amount of burned H.E. On the base witness plate there was a tailfin imprint from the detonation of the donor round.

TEST NO: KAA0331H1


DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST

FRAGMENTS OF ACCEPTOR PROJECTILES RECOVERED AFTER TEST






BASE WITNESS PLATE AFTER TEST

TEST: KAA0331I1

DATE: 31 MARCH 1981 TIME: 1600 MST



 $Xr + \delta = 15.88mm$ 

(Witness plates are 2.67mm thick mild steel)

RESULTS: Neither of the acceptor rounds detonated. The witness panel adjacent to  $A_1$  had no perforations and a small amount of unburned explosive deposited on it. The witness panel adjacent to  $A_2$  had two large perforations, and some burned explosive was deposited on it. There was a tailfin imprint on the base witness plate left by the detonation of the donor round only.

TEST NO: KAA0331I1


DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST








BASE WITNESS PLATE AFTER TEST

TEST: KAA0331J1 DATE: 31 MARCH 1981 TIME: 1645 MST



RESULTS: Acceptor  $A_1$  detonated. The witness panel adjacent to  $A_1$  had many small perforations; no explosive was deposited on it. The witness panel adjacent to  $A_2$  had one large perforation and some burned explosive was deposited on it. The witness panel adjacent to  $A_3$  had several large perforations, and no explosive was deposited on it. There were tailfin imprints left by the detonation of the donor and acceptor  $A_1$ .

TEST NO: KAA0331J1

DATE: 31 MARCH 1981



DONOR AND ACCEPTOR PROJECTILES BEFORE TEST




FRAGMENTS FROM ACCEPTOR
PROJECTILES RECOVERED AFTER TEST

TEST NO: KAA0331J1

DATE: 31 MARCH 1981



WITNESS PANEL WHICH STOOD ADJACENT TO ACCEFTOR PROJECTILE, A<sub>1</sub>



BASE WITNESS PLATE AFTER TEST

#### DISTRIBUTION LIST

No. of Copies		No. of Copies	Organization
12	Commander Defense Technical Info Center ATTN: DDC-DDA Cameron Station Alexandria, VA 22314	US a	mander Army Armament Research and Development Command N: DRDAR-TSS (2 cys) DRDAR-LCE, Dr. R.F. Walker DRDAR-LCE, Dr. N. Slagg
2	Chairman DOD Explosives Safety Board ATTN: Dr. T. Zaker Mr. P. Price	Dov	DRDAR-LCM, Mr. R. Rindner DRDAR-LCM, Mr. W. Stirrat er, NJ 07801
	Hoffman Bldg. I, Rm 856-C 2461 Eisenhower Avenue Alexandria, VA 22331	US R	mander Army Armament Materiel Readiness Command N: DRSAR-LEP-L, Tech Lib
1	HQDA (DAMA, E. Lippi) Washington, DC 20310		DRSAR-LC, Mr. L. Ambrosini Mr. W. Fortune Mr. R. Freeman
1	HQDA (DAPE-HRS, J. Coakley) Washington, DC 20310		k Island, IL 61299
1	Commander Ballistic Missile Defense Advanced Technology Center ATTN: Dr. David C. Sayles P. O. Box 1500	Ben ATT	Army ARRADCOM  Let Weapons Laboratory L. DRDAR-LCB-TL  Lervliet, NY 12189
	Huntsville, AL 35808	US	mander Army Aviation Research
1	Commander in Chief US Army Europe and Seventh Army ATTN: AEAGA-BE/Mr. P.Moran, Jr. APO, New York 09403	ATT 430	and Development Command TN: DRDAV-E 00 Goodfellow Boulevard Louis, MO 63120
1	Commander US Army Materiel Development and Readiness Command ATTN: DRCDMD-ST 5001 Eisenhower Avenue Alexandria, VA 22333	US a Ame	rector Army Air Mobility Research and Development Laboratory es Research Center Efett Field, CA 94035
1	Commander US Army Materiel Development and Readiness Command ATTN: DRCDE-DW, Mr. S.R. Matos 5001 Eisenhower Avenue	US ATT	nmander Army Communications Rsch and Development Command TN: DRDCO-PPA-SA rt Monmouth, NJ 07703

Alexandria, VA 22333

#### DISTRIBUTION LIST

No. of Copies		No. of Copies	
1	Commander US Army Electronics Research and Development Command Technical Support Activity ATTN: DELSD-L Fort Monmouth, NJ 07703	1	Director US Army TRADOC Systems Analysis Activity ATTN: ATAA-SL, Tech Lib White Sands Missile Range NM 88002
1	Commander US Army Missile Command ATTN: DRSMI-R Redstone Arsenal, AL 35809	1	Commander Office of Naval Research ATTN: Dr. J. Enig, Code 200B Arlington, VA 22217
1	Commander US Army Missile Command ATTN: DRSMI-YDL Redstone Arsenal, AL 35809	1	Commander Naval Sea Systems Command ATTN: Mr. R. Beauregard, SEA 64E Washington, DC 20362
1	Commander US Army Missile Command ATTN: DRSMI-RK, Dr. R.G.Rhoades Redstone Arsenal, AL 35809	2	David W. Taylor Naval Ship Research & Development Center ATTN: Dr. F. Fisch
1	Commander US Army Tank Automotive Rsch and Development Command ATTN: DRDTA-UL		Dr. S. L. Wang 6415 Bradley Boulevard Bethesda, MD 20084
1	Warren, MI 48090 Commander	1	Commander Naval Surface Weapons Center ATTN: Code G13
1	Tooele Army Depot ATTN: F. Crist		Dahlgren, VA 22448
	Tooele, UT 84074	9	Commander Naval Surface Weapons Center
1	Program Manager M1 Abrams Tank System ATTN: DRCPM-GCM-S Warren, MI 48090		ATTN: Mr. L. Roslund, R122 Mr. M. Stosz, R121 Code X211, Lib E. Zimet, R13 R.R. Bernecker, R13
1	Commander US Army Research Office ATTN: Chemistry Division P. O. Box 12211		J.W. Forbes, R13 S.J. Jacobs, R10 K. Kim, R13 M. Swisdak
	Research Triangle Park NC 27709		Silver Spring, MD 20910

#### DISTRIBUTION LIST

No. of Copies		No. of Copies	Organization
3	Commander Naval Weapons Center ATTN: Dr. L. Smith, Code 3205 Dr. A. Amster, Code 385 Dr. R. Reed, Jr., Code 38 China Lake, CA 93555	Univers: ATTN: I	e Livermore National Lab ity of California Dr. M.Finger re, CA 94550
1	Commander Naval Explosive Ordnance Disposal Facility ATTN: Tech Lib, Code 604 Indian Head, MD 20640	Los Alar ATTN: P. O. Bo Los Alar	mos National Lab Dr. B. Craig, M. Division
1	Commander Naval Research Laboratory ATTN: Code 6100 Washington, DC 20375	Dir, US ATTN:	AMSAA DRXSY-D DRXSY-MP, H. Cohen
1	Commanding General Fleet Marine Force, Atlantic ATTN: G-4 (NSAP) Norfolk, VA 23511	Dir, US	ATECOM DRSTE-TO-F ACSL, B1dg. E3516, EA DRDAR-CLB-PA
1	AFRPL/MKPA (Mr. R. Geisler) Edwards AFB, CA 93523		

#### USER EVALUATION OF REPORT

Please take a few minutes to answer the questions below; tear out this sheet, fold as indicated, staple or tape closed, and place in the mail. Your comments will provide us with information for improving future reports.

1. BRL Report Number
2. Does this report satisfy a need? (Comment on purpose, related project, or other area of interest for which report will be used.)
3. How, specifically, is the report being used? (Information source, design data or procedure, management procedure, source of ideas, etc.)
4. Has the information in this report led to any quantitative savings as far as man-hours/contract dollars saved, operating costs avoided, efficiencies achieved, etc.? If so, please elaborate.
5. General Comments (Indicate what you think should be changed to make this report and future reports of this type more responsive to your needs, more usable, improve readability, etc.)
6. If you would like to be contacted by the personnel who prepared this report to raise specific questions or discuss the topic, please fill in the following information.
Name:
Telephone Number:
Organization Address: